

**CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED**

## Sheduled Outage Information

Details of Power shut down due to maintenance of distribution system

Sl.No	Date of Outage	Name of Town	Name of Sub-station	Name of Feeder	Area Affected	From(HH:MM)	To(HH:MM)
1	10.12.18	Haradanahalli, Gundlupete & Beguru	66/11KV MUSS Harve, Kabbahally, Gundlupete, Beguru, Bommalapura	Mudnakudu, Mukkadahally, Udigala, Nanjadevanapuara, Kalpura, Devalapura, Tmmadahally, NJY, Padguru, Nenekatte, Veeranapura, Gundlupete,	Mudnakudu, Mukkadahally, Udigala, Nanjadevanapuara, Kalpura, Devalapura, Tmmadahally, NJY, Harve, Kerahally, Kebbepura, Padguru, Nenekatte, Veeranapura, Gundlupete, Channodayanapura, Hasuguli, Kabballi, Beguru in surrounding places.	10.00	6.00