

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	15.03.2018	N.R.Mohalla Division.	66/11 KV DK Maidana MUSS	Bhuvaneshwari & Suttur	Gowrishankarnagar, Muneshwarnagar, Gunduraonagar, Dattnagar, Sachhidanandnagar, Jaki vasatigraha, Tavarekatte, Chamundibetta and surrounding areas	10:00	17:00
2		Holenarasipura	Hallymysore	F8 Hallymysore	Hallymysore, Gohalli	10:00	18:00
3		Mysore	66/11kV Vijayanagara	Chandramouleswara & Jayalaxipuram	Vidyavardaka Engineering College Road,Chandrakala Hospital Road, Temple Road,Kd Road,Gokulam Main Road,Hunsur Road,Mathrumandali Circle,Adipampa Road,Vamiki Road,Dc House,Kalamandir,Cftri,Regional Office,Nurse Quarters,Lic,Vobtikoppal,Vinayakanagara,Paduvarahalli,Vijayanagara 1st Stage,Kuvempu Trust	10:00	17:00