

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area, À Affected	From (HH:MM)	To (HH:MM)
1	20.10.2019	Bilikere	66/11kv Bilikere	Alanahally, Manuganahally, Tenkanakoppalu, Ayarahalli, Challahalli, Gagenahalli, DRDO, Mullur, Kyathanahalli, Bilikere, Halebeedu	Alanahalli, Manuganahalli, Tenkanakoppalu, Ayarahalli, Challahalli, Gagenahalli, DRDO, Kyathanahalii, Bilikere town, Halebeedu, Mallinathapura, Vaddarahalli, Sabbannahalli, Gomatgiri	10:00	17:00
2		Mandya Sub division	66/11KV CHIKKA MANDYA	SUGAR	Mandya City area : Jain street, Devegowdanadoddi, Jabbar circle, railway station road	9:30	17:00