

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	22.01.2018	N.R.Mohalla Division.	66/11 KV Vajamangala MUSS	Police Layout	Bhugatalli, Choranahalli, Chikkahalli, Police Layout.	10:00	17:00