

CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Sub-div	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	25.05.2018	Mysore	66/11kV KHB	K.H HALLI & V2	Belavadi Village,Basavanapura,Vijayanagara Svei School And Surrounding Areas	10:00	17:00
2		Mysore	66/11kV SOUTH MUSS	Saraswathipuram	Jayanagara,Chikkanahalli,Kuvempuna gara,K Block,Srirampura,Naidu Store,Saraswathipuram 1 To 5th Main Road,Kg Koppal,University Quarters,Saraswathi Theatre And Surrounding Areas	10:00	17:00