

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	28.10.2017	N.R.Mohalla Division.	220/66/11 KV Vajamangala	Mayabandar, Vidya vikas, Mellahalli, Police Layout, Varakowu, Vajamangala	Halagaiahnahundi, Mellahalli, Vajamangala, Varakodu, Sajjehundi, Dandikere, Varuna, Chorannahalli, Chikkahalli, Kempegowdanahundi, Police Layout, Bhugatagalli	10:00	18:00