

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	30.01.2018	N.R.Mohalla Division.	66/11 KV South (Mysuru) MUSS	Lakshmipuram,RTO,KM P,LF-3	Sheetharangara road, Lakshmipuram, Hosakeri, Rehamanya Mohalla, Sunnadakeri, Jain Bhavan, Kakalavadi, Diwans road, Ashokapuram, Krishnamurthipuram, Chamarajapuram, Ballal circle, Chamundipuram.	10:00	17:00